Qty:

3 Um:

Each



Monday, 11/08/2008 1:02:30 PM

Melanie Fauteux

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

Job Number **Estimate Number**

: 41110 : 13543

P.O. Number

: 11/08/2008 This Issue

: NC Prsht Rev.

First Issue : // : 41010

Previous Run

Written By

Checked & Approved By

: Est Rev:A

DD verified by:ec new issue

: R & D SM/MED FAB

Additional Product

PRELIMINARY ISSUE

: 412 SKI WEARPLATE

: D3796 REV.A PREL

: D3796043

: N/A

: PRELIM

: 18/08/2008

Job Number:

Comment



Seq. #:

Description: 304/316 Sheet .063

1.0

M304S16GA



Comment: Qtv.:

6.0228 sf(s) 2.0076 sf(s)/Unit Total:

NEOPRENESHEET 0.063 304

batch: 108774

2.0

WATER JET

Comment: FLOW WATER JET

1-Cut as per Dwg D3796

Dwg Rev: RE

1B 8-8-11

Prog Rev: ORF

2-Deburr if necessary

138-8-11

QC2 3.0

B8-8-11

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK

INSPECT PARTS AS THEY COME OFF MACHINE

Comment: SECOND CHECK

5.0 D30093



Comment: Qtv.:

12.0000 Each(s)/Unit Total:

36.0000 Each(s)

Cup

batch:

Page 1

Form: rprocess

Date:	Monday, 11/08/2008 1: Melanie Fauteux	02:30 PM			
معلقة، بريد			Process Sheet	WEADNIATE	
-, Cust	omer: CU-DAR001 Dart	Helicopters Services	Drawing Name: 412 SKI	WEARPLATE	
Job Nu	mber: 41110		Part Number: D379604	3	
Job Numbe	er:				
Seq. #:	Machine Or Ope	ration:	Description	:	
6.0 C	Comment: LARGE FABR	RICATION RESOURCE 1	SS ROD BH MIO7 JOS9B BH MIO8		
7.0		t (template DT9037) and cup	visual welding inspection	EL 8-8"	7
	comment: VISUAL WEL	DING INSPECTION	Cpl 08.08.14		(XZ)
8.0			INSRECT WORK TO CHERENT STEP	1 100 110 1010 11010 1011 1011	
	Comment: INSPECT WO	DRK TO CURRENT STEP	AFPROVAL	2	\$00.05.20
9.0 C	PACKAGING 1	RESOURCE #1	PACKAGING RESOURCE #1		
	Identify and S Location:		8/8/	18	SU
10.0 C		CTION/W/O RELEASE	FINAL INSPECTION/W/O RELEASE		08/09/09
Job Completio	on			IVE RECALL	1 <u>U</u>
		nt grey As per	duy Stort:		1 / ~/~/.
8.7	2 QC3.	HD08-08	- 14 Rinishid	1080208	N 95/14

DART AEROSPACE LTD	Work Order: 41110
Description: 412 SK, WEARD	Part Number: 03796-3
Inspection Dwg: D2796-3 Rev: DRE	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
\$. 879	100, -010. +	.880	χ÷			
375	4- 1030	3,754	×			
000,2	4/ .010	5.000	Y			
6.34	4/_ ,030		Æ			
3.000	4,010		۴			
8,500	7010	8.500	X			
9.667	1/2 .010	9.666	1			
696.01	th010		×			
21,750	4/ .010	21.70	×			
33,000	4 010	32000	×			
43 47	1/2 030	42.93	X 0			
,063	4010	,057	×			
					·	
·						
	ŧ					
			,			
	,					

					,/	
Measured by:	B	Audited by:	5,,	Prototype Approval:	1	
Date:	8-8-11	Date:	0469/12	Date:	16	<u> </u>

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	









